Inspection Report

Name of Work	: Improvements to Roads in Behind Ayyapa Swamy Temple Jakkur Layout in Ward No.07 Byatarayanapura, Kodigehalli Sub Division
Work Order	: EE/BTP/BBMP/E-PMT/WO/236/2014-15, Dated:23.01.2015
Agency	: Gnanendra Reddy
B.R.No & Date	: 291/2015-16, Dated: 31.03.2016
Bill Amount	: 9,78,787.00
Job Code	: 007-15-000017
P.Code	: P-1771
Date of Inspection	: 16-05-2016

The above said work Improvements to Roads in Behind Ayyapa Swamy Temple Jakkur layout in ward 07 Byatarayanapura, Kodigehalli Sub Div was shown to me by the Concerned ward Engineer.

The above said work is inspected by me along with the Concerned ward Engineer.

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Improvements to Roads in Behind Ayyapa Swamy Temple Jakkur Layout in Ward No.07, Byatarayanapura, Kodigehalli Sub Division



MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Improvements to Roads in Behind Ayyapa Swamy Temple Jakkur Layout in Ward No.07, Byatarayanapura, Kodigehalli Sub Division

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT